

Linear Technology Korea

Tel. 02-792-1617
Email. kwkim@linear.com

/ Perrien Worldwide
Tel. 017-427-8279 (02-812-1144)
Email. desiree@perrien.co.kr

, 4MHz,
4mm x 4mm QFN 3A

2005 11 30 - (, www.linear.com)가
4MHz, (: LTC3412A)
. 4mm x 4mm QFN (TSSOP-16)
0.8V 3A .
LTC3214A 2.25V ~ 5.5V
NiMHz .
가 4MHz 가 1.5mm 가
. LTC xDSL
xDSL , .
LTC3412A $R_{DS(ON)}$ 0.065 ~ 0.077 95%
. 100% ,
(No load quiescent current)
64uA , 1uA .
LTC3412A (Burst
Mode[®])
가
, SYNC/MODE RF
(Power Good) ,
. LTC3412A 3A 가
LTC3412A QFN-16 16 TSSOP
가 1 4.10 .

LTC3412A

- 95%
- 3A
- : 64uA
- RDS(ON)가 : 77m
- : 2.25V ~ 5.5V
- : 300KHz ~ 4MHz
- $\pm 2\%$
- 0.8V 가
- / 가
- 가 가
- : 100%
-
-
- 16 TSSOP & QFN-16

2000 IC 1981 1986 ,
 S&P 가 ,
 , , , , , DC-DC ,
 , , , , RF ,
 , , (,
), , / , , ,
 (MP3), , , , ,

Doug Dickinson, Media Relations Manager

Linear Technology Corporation

1630 McCarthy Boulevard

Milpitas, CA 95035-7417

ddickinson@linear.com

408-432-1900

: 1-800-4-LINEAR ()
<http://www.linear.com>

: LT, LTC, Burst Mode



Linear Technology Corp.